

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 11/21/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294, Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Pure Gold B Federal #4	Facility Type	Well
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-27238

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	20	23S	31E					Eddy

Latitude N 32.28449° Longitude W 103.79334°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	15 bbls oil, 2 bbls produced water	Volume Recovered	10 bbls
Source of Release	Livestock broke off well head sensor nipple	Date and Hour of Occurrence	07/14/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Jennifer Gilkey @ BBC International Inc.	Date and Hour	07/14/2016 @ 4:28 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Livestock broke off the well head sensor nipple causing a release of 15 bbls of oil and 2 bbls of produced water. A vacuum truck recovered 10 bbls of fluids and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 150' x 50' both on and off location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/28/2016 and approved by Shelly Tucker of the BLM via email on 10/04/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Casey Summers		
Title:	NM Environmental Advisor	Approval Date:	12/2/2016
E-mail Address:	Casey_Summers@oxy.com	Expiration Date:	N/A
Date:	11-16-16	Conditions of Approval:	FINAL
Phone:	(575) 513-8289	Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3795