District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

NMOCD Dist 2 State of New Mexico **Energy Minerals and Natural Resources**

Received 1/17/2017

Form C-141

<REVISED>

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

AB1701351977	OPERATOR 🛛			Initial Report 🛛 Final Report		
Name of Company:	Contact: Robert McNeill					
			Telephone No. 432-683-7443			
Facility Name: Puckett 13 Federal Tank Battery H			Facility Type: Tank Battery			
Surface Owner: Federal Mineral Owner:			API No. 30-015-40737			
	LOCATIO	N OF REI	LEASE			
Unit Letter Section		h/South Line	Feet from the	East/West Line	County	
P 12	17S 31E 43	South	590	East	Eddy	
	Latitude 32.842010	05 Longitue	ie 103.8164825			
	NATURE	COF REL			0.01 0.024	
Type of Release: Oil and Produced Water			Volume of Release: Volume Recovered: 2 bbls Oil & 3 bbls PW 1 bbls Oil & 2 bbls PW			
Source of Release:					Hour of Discovery:	
Portable Tester			January 6, 2017 7:00 pm January 6, 2017 7:00 pm			
Was Immediate Notice G	iven?	If YES, To	Whom?			
		Date and Hour:				
Was a Watercourse Reached?			If YES, Volume Impacting the Watercourse.			
☐ Yes ⊠ No						
If a Watercourse was Imp	acted, Describe Fully.*					
D 11 0 (D 11					31	
Describe Cause of Proble	m and Remedial Action Taken.*					
The release was due to a j	pop off valve on a portable tester. The portable	tester was rem	oved from servic	e.		
Describe Area Affected a	nd Cleanup Action Taken.* REVISIO]	N:				
The release occurred on t	he pad and into the adjacent pasture. A vacuum	truck was dis	patched to remove	e all freestanding flu	uids. Concho will have the spill	
area sampled to delineate	any possible impact from the release and we w					
significant remediation ac		1 1 0				
	nformation given above is true and complete to are required to report and/or file certain release					
	onment. The acceptance of a C-141 report by the					
should their operations ha	ave failed to adequately investigate and remedia	ate contaminati	ion that pose a thr	eat to ground water	, surface water, human health	
	dition, NMOCD acceptance of a C-141 report	does not reliev	e the operator of	responsibility for co	ompliance with any other	
federal, state, or local law				SEDVATION		
Signature: Leheco		OIL CONSERVATION DIVISION				
Printed Name:	Rebecca Haskell	Annroved by	Approved by Environmental Specialist:			
Title:	Senior HSE Coordinator	Approval Da	te: 1/ 10/ 17	Expiration	Date:	
E-mail Address:	rhaskell@concho.com	Conditions of Approval: Same COA as origina submittal		1	Attached	
Date: January 17, 2017	Phone: 432-683-7443			original		
Attach Additional Shee		su su	omittai		ADD 4072	
					2RP-4073	