

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1718634277

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC OGRID #217955	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Diamondback 22 State Com #002H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-38528
----------------------	----------------------	----------------------

LOCATION OF RELEASE

API number is for well # 1H

Unit Letter D	Section 22	Township 26S	Range 28E	Feet from the 580	North/South Line North	Feet from the 580	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.0336304 Longitude -104.0818634

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 15 bbls	Volume Recovered: 14.5 bbls
Source of Release: Filter Pot	Date and Hour of Occurrence: June 19, 2017 12:00 pm	Date and Hour of Discovery: June 19, 2017 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was due to a one-inch nipple and valve on the filter pot popping off while the transfer pump was running. Replaced fittings with stainless steel ones.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheldon Hitchcock</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock	Accepted for Record	
Title: HSE Coordinator	Approved by Environmental Specialist: Accepted for Record Approval Date: 10/24/17	Expiration Date: N/A
E-mail Address: slhitchcock@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/13/2017 Phone: 575-748-0233		

* Attach Additional Sheets If Necessary

NOTE: Spill was reported on well # 1H but actually occurred on well # 2H
API number and entry is for well # 1H

2RP-4275