

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1629838248

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	RIVERBEND FEDERAL #5	Facility Type	WELL

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-015-27977
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	22	24S	29E					EDDY

Latitude N 32.20418' Longitude W 103.96664' NAD83

NATURE OF RELEASE

Type of Release	PRODUCED WATER	Volume of Release	65 BBLS	Volume Recovered	50 BBLS
Source of Release	Compromised water transfer line	Date and Hour of Occurrence	10/11/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER-NMOCD; HEATHER PATTERSON-NMOCD; SHELLY TUCKER-BLM			
By Whom?	KATY @ BBC INTERNATIONAL INC	Date and Hour	10/12/16 @ 4:38 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A compromised water transfer line leaked 65 bbls of produced water into the pasture north of location. A vacuum truck recovered 50 bbls of produced water and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 125' x 45', just north of location in the pasture. Remediation was completed in accordance with a remediation plan approved by both NMOCD (MIKE BRATCHER - 9-20-17) and the BLM (SHELLY TUCKER 10-3-17).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: 	
Title: ENVIROMENTAL SPECIALIST	Approval Date: 1/8/2018	Expiration Date: N/A
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval: Like Approval BLM	
Date: 12-20-17 Phone: 575-390-2828	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3949