

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received on  
12/7/2017  
OCD Artesia, NM  
District II

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: <b>COG Operating, LLC (OGRID# 229137)</b>	Contact: <b>Robert McNeill</b>
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No.: <b>432-683-7443</b>
Facility Name: <b>Patron 23 Federal #004H</b>	Facility Type: <b>Flowline</b>
Surface Owner: <b>BLM</b>	Mineral Owner: <b>Federal</b>
API No.: <b>30-015-42451</b>	

#### LOCATION OF RELEASE

Unit Letter <b>P</b>	Section <b>14</b>	Township <b>25S</b>	Range <b>29E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude: 32.1222382 Longitude: -103.9487228 NAD83

#### NATURE OF RELEASE

Type of Release: <b>Produced Water</b>	Volume of Release: <b>200bbls</b>	Volume Recovered: <b>0bbls</b>
Source of Release: <b>Flowline</b>	Date and Hour of Occurrence: <b>January 28, 2017 11:00am</b>	Date and Hour of Discovery: <b>January 28, 2017 11:00am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Ms. Weaver-NMOCD</b> <b>Ms. Tucker-BLM</b>	
By Whom? <b>Rebecca Haskell</b>	Date and Hour: <b>January 28, 2017 5:11pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release was due to a rupture in a flowline. The damaged section of flowline was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release impacted the pasture northeast of the Patron 23 Federal #004H location. The impacted area was evaluated and a remediation work plan was subsequently drafted and approved by NMOCD & BLM. The remediation was carried out in accordance with the approved work plan and stipulations agreed upon by NMOCD & BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheldon Hitchcock</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Sheldon L. Hitchcock</b>		Approved by Environmental Specialist: <i>Crystal Wee</i>	
Title: <b>HSE Coordinator</b>	Approval Date: <b>2/13/2018</b>	Expiration Date: <b>N/A</b>	
E-mail Address: <b>slhitchcock@concho.com</b>	Conditions of Approval: <b>FINAL</b>		Attached <input type="checkbox"/>
Date: <b>12/7/2017</b>	Phone: <b>575-746-2010</b>		

\* Attach Additional Sheets If Necessary

2RP-4096