

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Received 10/26/2017
NMOCD Dist 2

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1635756020

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443
Facility Name: Graham Nash State Com #008H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-42203
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	28	26S	28E	190	North	760	West	Eddy County, NM

Latitude N 32.02034° Longitude W 104.09850°

NATURE OF RELEASE

Type of Release: Oil & produced water	Volume of Release: 40 bbls oil, 30 bbls produced water	Volume Recovered: 39 bbls oil, 27 bbls produced water
Source of Release: Ball valve	Date and Hour of Occurrence 12/18/2016 @ 7:00 am	Date and Hour of Discovery 12/18/2016 @ 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver, Mike Bratcher, and Heather Patterson- NMOCD; Amber Groves- NMSLO	
By Whom? Robert Grubbs Jr.	Date and Hour: 12/19/2016 @ 2:24 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused by a corroded ball valve due to age. The ball valve has been replaced with a new one.

Describe Area Affected and Cleanup Action Taken.*
The release was mostly contained within the lined facility and a small area 24' x 30' on the pad. A vacuum truck was dispatched to remove all freestanding fluids.. The site was delineated according to OCD standards and a remediation plan was created. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/01/2017 and approved by Amber Groves of the SLO via email on 09/18/2017.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	OIL CONSERVATION DIVISION		
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>Mike Bratcher</i>		
Title: Senior HSE Coordinator	Approval Date: 3/20/18	Expiration Date: N/A	
E-mail Address: rhaskell@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: October 24, 2017	Phone: (432) 683-7443		

* Attach Additional Sheets If Necessary

2RP-4043