

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/2/2018
NMOCD Dist 2

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1421854563

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company XTO Energy	Contact Kyle Littrell	
Address 3104 E Greene Street Carlsbad, N.M. 88220	Telephone No. 432-221-7331	
Facility Name Big Eddy Unit 164 Tank Battery	Facility Type Exploration and Production	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-35592

LOCATION OF RELEASE

Unit Letter J	Section 27	Township 21S	Range 29E	Feet from the 1650	North/South Line South	Feet from the 1650	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.447365 Longitude -103.968959 NAD83

NATURE OF RELEASE

Type of Release Produced Water and crude oil	Volume of Release 0.5 bbl Crude Oil and 10.5 bbl Produced Water	Volume Recovered 0 bbls
Source of Release Produced water tank	Date and Hour of Occurrence 7/27/14 time unknown	Date and Hour of Discovery 7/27/2014 @ 12:54 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*



The well unloaded and caused the water tank to overflow. Water hauler failed to off-load water. Pumper called the water transport company to verify when water needs to be hauled.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 515 sq. ft. of the earthen containment around the production tanks. All of the fluid soaked into the ground. The tanks were evaluated for relocation and placement inside O perm containment. The spill area will be cleaned up in accordance with the NMOCD and BLM remediation guidelines.

LTE collected six soil samples on February 26, 2018. Laboratory analytical results for the six soil samples indicated BTEX, TPH, and chloride were below the NMOCD remediation action levels for this site. XTO requests no further action for the release.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell		Approved by Environmental Specialist: 	
Title: SH&E Coordinator		Approval Date: 5/3/18	Expiration Date: N/A
E-mail Address: Kyle.Littrell@xtoenergy.com		Conditions of Approval: Like approval BLM	Attached <input type="checkbox"/>
Date: 5/01/2018 Phone: 432-221-7331		FINAL	

* Attach Additional Sheets If Necessary

2RP-2414