

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1703330360

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	CYPRESS 33 FEDERAL #1H	Facility Type	BATTERY
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-36321

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	23S	29E					EDDY

Latitude N 32.25539 Longitude W 103.98216 NAD83

NATURE OF RELEASE

Type of Release	PRODUCED WATER	Volume of Release	60 bbls	Volume Recovered	40 bbls
Source of Release	FAULTY GASKET ON WATER TRANSFER PUMP	Date and Hour of Occurrence	01/20/2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER-NMOCD, CRYSTAL WEAVER-NMOCD, SHELLY TUCKER-BLM			
By Whom?	KATHY PURVIS @ BBC International Inc	Date and Hour 01/24/2017 @ 3:37 PM			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A faulty gasket on the water transfer pump caused a leak of 60 bbls of produced water. A vacuum truck recovered 40 bbls of produced water and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 300' x 50' on location. Remediation was completed in accordance with a remediation plan approved by both NMOCD (9-20-17) and the BLM (9-20-17).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: <i>Maria Pruett</i>		
Title: ENVIRONMENTAL SPECIALIST	Approval Date: 07/13/18	Expiration Date: N/A	
E-mail Address: WADE.DITTRICH@OXY.COM	Conditions of Approval: Like approval BLM		Attached <input type="checkbox"/>
Date: <u>2-9-18</u> Phone: 575-390-2828			

* Attach Additional Sheets If Necessary

FINAL

2RP-4097