

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

pAB1711050010

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA WTP LP	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-390-2828
Facility Name	GOVERNMENT AC 13 FEDERAL #5H	Facility Type	OIL WELL
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-40880

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	13	20S	28E	1980	NORTH	350	WEST	EDDY

Latitude\_32.5755501\_ Longitude\_-104.1384048\_ NAD83

#### NATURE OF RELEASE

Type of Release	OIL & PRODUCED WATER	Volume of Release	30 bbls OIL/5 bbls PW	Volume Recovered	30 bbls
Source of Release	STUFFING BOX PACKING FAILURE	Date and Hour of Occurrence	4-14-2017	Date and Hour of Discovery	4-14-2017
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER-NMOCD; CRYSTAL WEAVER-NMOCD; SHELLY TUCKER-BLM			
By Whom?	CASEY SUMMERS	Date and Hour	4-17-2017 10:20AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

LEAK IS DUE TO STUFFING BOX PACKING ON THE WELLHEAD BLOWING OUT. 30 BBLS OF RELEASED FLUID WERE INITIALY RECOVERED BY VACUUM TRUCK. STUFFIN BOX PACKING HAS BEEN REPLACED.

Describe Area Affected and Cleanup Action Taken.\*

THE AFFECTED AREA IS APPROXIMATELY 30' X 30' ON LOCATION (MEASUREMENTS ARE SUBJECT TO CHANGE BASED ON GPS TRACK). REMEDIATION WAS COMPLETED IN ACCORDANCE WITH A REMEDIATION PLAN APPROVED BY BOTH NMOCD (09/21/2017) AND THE BLM (10/03/2017).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: <i>Maria Pruett</i>		
Title: ENVIRONMENTAL SPECIALIST	Approval Date: 07/25/18	Expiration Date: N/A	
E-mail Address: wade.dittrich@oxy.com	Conditions of Approval: Like Approval BLM		Attached <input type="checkbox"/>
Date: <i>2-26-18</i> Phone: 575-390-2828			

FINAL

2RP-4180