

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

pAB1736131625

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: COG Production, LLC (OGRID 217955)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: Copperhead 31 Federal Com #003H	Facility Type: Tank Battery
Surface Owner: Private	Mineral Owner: Federal
API No.: 30-015-43924	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	30	26S	29E	349	North	773	East	Eddy

Latitude: 32.019787 Longitude: -104.01721 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20bbls	Volume Recovered: 18bbls
Source of Release: Tank overflow	Date and Hour of Occurrence: 12/18/2017 6:00am	Date and Hour of Discovery: 12/18/2017 6:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
A tank overflow occurred due to human error on the part of a 3 rd party contractor. The issues surrounding the human error were addressed to mitigate similar incidents in the future.		
Describe Area Affected and Cleanup Action Taken.*		
All of the fluid remained inside of the lined containment. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
 Signature:		<h3><u>OIL CONSERVATION DIVISION</u></h3> Approved by Environmental Specialist: <i>Maria Pruett</i>
Printed Name: Dakota Neel		
Title: HSE Coordinator	Approval Date: 07/25/18	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: Like Approval BLM	Attached <input type="checkbox"/>
Date: 3-5-2018	Phone: 575-746-2010	

* Attach Additional Sheets If Necessary

FINAL

2RP-4532