

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCD Rec'd:08/08/18

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC (OGRID #229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: <b>Burch Keely Unit #963H</b>	Facility Type: Wellhead	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-39576

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	19	17S	30E	893	North	358	West	Eddy

Latitude 32.8248863 Longitude -104.0184937 NAD83

### NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 5 bbl. Oil 15 bbl. Produced Water	Volume Recovered: 2 bbl. Oil 3 bbl. Produced Water
Source of Release: Obstructed Valve	Date and Hour of Occurrence: August 7, 2018 6:30am	Date and Hour of Discovery: August 7, 2018 6:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
The release was caused by debris obstructing the back pressure valve. The valve has been replaced.		
Describe Area Affected and Cleanup Action Taken.*		
The release impacted the location and the adjacent pasture. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: DeAnn Grant	Approved by Environmental Specialist: Maria Pruett	
Title: HSE Administrative Assistant	Approval Date: 08/11/18	Expiration Date: N/A
E-mail Address: agrant@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: August 7, 2018	Phone: 432-253-4513	2RP-4916

\* Attach Additional Sheets If Necessary

A#: pMAP1822343592

I#: nMAP1822343714