State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

OCD Rec'd: 08/17/18

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

	Santa Fe,	NM 87505	
Release	Notification a	and Correc	tive Action

	OPERATOR	Initial Report	Final Report
Name of Company Devon Energy Production	Contact Mike Shoemaker		
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-748-3371		
Facility Name Ore Ida 14 Fed 10	Facility Type Oil		

Surface Owner Federal

Mineral Owner Federal

API No. 30-015-29290

LOCATION OF RELEASE

Unit Letter Se	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
Ι	14	24S	29E	1980	South	660	East	Eddy

Latitude: N 32'21'53.45"

Longitude: W 103'94'90.29"

NATURE OF RELEASE

Type of Release Spill	Volume of Release	Volume Recovered				
Produced Water and Oil	85 bbls	60 bbls				
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery				
Pump malfunction	8/21/2015 @ 10:41 PM	8/21/2015 @ 10:41 PM				
Was Immediate Notice Given?	If YES, To Whom?					
Yes D No D Not Required	BLM					
OCD OCD						
By Whom?	By Whom? Date and Hour					
David Simmons	August 21, 2015 @ 11:26 PM					
August 21, 2015 @ 11:31 PM						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse					
\Box Yes \boxtimes No						
If a Watercourse was Impacted, Describe Fully.*						
Describe Cause of Problem and Remedial Action Taken.*						
Lease operator arrived at location and discovered that the water tank was of	e e .	•				
containment. The pump was reset and within a minute the tank stopped from over flowing. Black River Trucking was called out and they were able to						
recover 60 bbls of produced water and oil.						
Describe Area Affected and Cleanup Action Taken.*						
The release was contained to the well pad. The facility infrastructure was removed. Remediation activities were carried out in accordance with NMOCD						
guidelines. Upon NMOCD approval of confirmation sample results, the excavation was backfilled and contoured to match the surrounding location. A						
closure report detailing remediation activities is provided.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and						
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger						
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability						
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health						
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other						
federal, state, or local laws and/or regulations.						

Tederal, State, of Tetal and, of Tegulations,						
	OIL CONSERVATION DIVISION					
Signature: Michael Shoemaker			11111			
Drives J Manage Michael Charman	Approved by Environmental Specialist:					
Printed Name: Michael Shoemaker	Approved by Environmental Specialist.					
Title: Environmental Professional	Approval Date: 08/20/18	Expiration Date: N/A				
E-mail Address: mike.shoemaker@dvn.com	Conditions of Approval:		Attached			
Date: 8/25/2015 Phone: 575.746.5559	Like Approval BLM					

* Attach Additional Sheets If Necessary

FINAL 2RP-4123