

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443	
Facility Name: SRO State Com #017H (Illegal Dump)	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No. 30-015-38257

LOCATION OF RELEASE

Unit Letter D	Section 09	Township 26S	Range 28E	Feet from the 990	North/South Line North	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.061676 Longitude -104.0999146 NAD83

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release Estimated 25 bbl.	Volume Recovered 0 bbl.
Source of Release Illegal Dump	Date and Hour of Occurrence August 16, 2018 11:30am	Date and Hour of Discovery August 16, 2018 11:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Maria Pruett – NMOCD Mike Bratcher – NMOCD Ryan Mann - SLO	
By Whom? DeAnn Grant	Date and Hour August 16, 2018 3:57pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The spill was an illegal dump on a COG location.

Describe Area Affected and Cleanup Action Taken.*

The release occurred on location. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant		Approval Date: 08/20/18	Expiration Date: N/A
E-mail Address: agrant@concho.com		Conditions of Approval:	
Date: August 16, 2018 Phone: (432) 253-4513		Attached <input type="checkbox"/> 2RP-4930	

* Attach Additional Sheets If Necessary

A#: pMAP1823236506

I#: nMAP1823236654