

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating, LLC (229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-683-7443
Facility Name: <b>Screech Owl Federal #004H</b>	Facility Type: Flowline

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42828
------------------------	------------------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	18	26S	27E					Eddy

Latitude 32.0352751 Longitude -104.2249731 NAD83

### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 bbl.	Volume Recovered 0 bbl.
Source of Release Flowline Leak	Date and Hour of Occurrence August 18, 2018 12:00pm	Date and Hour of Discovery August 18, 2018 12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – NMOCD Maria Pruett – NMOCD Shelly Tucker – BLM	
By Whom? Robert McNeill	Date and Hour August 19, 2018 12:27pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by a flowline leak. The flowline is being replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred alongside the lease road and in the pasture. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: DeAnn Grant		Approved by Environmental Specialist: 	
Title: HSE Administrative Assistant		Approval Date: 08/21/18	Expiration Date: N/A
E-mail Address: agrant@concho.com		Conditions of Approval:  N/A	Attached <input type="checkbox"/> 2RP-4944
Date: August 20, 2018	Phone: (432) 253-4513		

\* Attach Additional Sheets If Necessary

A#: pMAP1823331576

I#: nMAP1823331695