

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: SRO State Com #013H	Facility Type: Tank Battery
Surface Owner: State	Mineral Owner: State
API No.: 30-015-37427	

LOCATION OF RELEASE

Unit Letter D	Section 15	Township 26S	Range 28E	Feet from the 660	North/South Line North	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.0478973 Longitude: -104.0828857 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 60bbls	Volume Recovered: 55bbls
Source of Release: Lightning Strike	Date and Hour of Occurrence: July 31, 2017 12:00am	Date and Hour of Discovery: July 31, 2017 12:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD Mark Naranjo-NMSLO	
By Whom? Rebecca Haskell	Date and Hour: August 1, 2017 3:07pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
A lightning strike caused damage to a produced water tank resulted in the release of approximately 60bbls of produced water.		
Describe Area Affected and Cleanup Action Taken.*		
The release affected the lined containment and the adjacent pasture. A vacuum truck was utilized to recover freestanding fluid. The impacted area in the pasture was evaluated and a remediation work plan was drafted and subsequently approved by NMOCD and NMSLO. The remediation was carried out in accordance with the approved work plan.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Sheldon Hitchcock</i>		OIL CONSERVATION DIVISION
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist: <i>[Signature]</i>
Title: HSE Coordinator	Approval Date: 09/10/18	Expiration Date: n/a
E-mail Address: slhitchcock@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/31/2018	Phone: 575-746-2010	N/A

* Attach Additional Sheets If Necessary

A#:pAB1721456076

FINAL-2RP-4313

I#:nAB1721456546