

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCD Rec'd:08/31/18

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443	
Facility Name: SRO State Com #013H	Facility Type: Tank Battery	
Surface Owner: State	Mineral Owner: State	API No.: 30-015-37427

LOCATION OF RELEASE

Unit Letter D	Section 15	Township 26S	Range 28E	Feet from the 660	North/South Line North	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.0478973 Longitude: -104.0828857 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 19bbbls	Volume Recovered: 0bbbls
Source of Release: 3" tee	Date and Hour of Occurrence: August 17, 2017 11:00am	Date and Hour of Discovery: August 17, 2017 11:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
A three inch tee failed due to corrosion resulting in the release of approximately 19bbbls of produced water.		
Describe Area Affected and Cleanup Action Taken.*		
The release affected the pasture adjacent to the battery. The impacted area in the pasture was evaluated and a remediation work plan was drafted and subsequently approved by NMOCD and NMSLO. The remediation was carried out in accordance with the approved work plan.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Sheldon Hitchcock</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: HSE Coordinator		Approval Date: 09/10/18	Expiration Date: N/A
E-mail Address: slhitchcock@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/31/2018	Phone: 575-746-2010	N/A	

* Attach Additional Sheets If Necessary

A#: pAB1723328502

I#: nAB1723328585

FINAL-2RP-4328