

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAB1904453396
District RP	1RP-5365
Facility ID	
Application ID	pAB1904451625

Release Notification

Responsible Party

Responsible Party <i>Breithorn Operating, LP</i>	OGRID <i>270080</i>
Contact Name Thomas Haigood	Contact Telephone (432) 701-7802
Contact email Thomas.haigood@maurresources.com	Incident # (assigned by OCD) NAB1904453396
Contact mailing address PO Box 678 Andrews, TX	

Location of Release Source

Latitude 32.400517 Longitude -103.337703
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Jalmat Field Yates Unit #225	Site Type Pipeline
Date Release Discovered 02/07/2019** <i>AB</i>	API# (if applicable) 30.025.38704

Unit Letter	Section	Township	Range	County
J	10 11** <i>AB</i>	22S	35E	Lea

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude	Volume Released (bbls) 17	Volume Recovered (bbls) 10
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: A bullet struck the poly flow line heading from the Jalmat #225 well to the production facility.

State of New Mexico
Oil Conservation Division

Incident ID	NAB1904453396
District RP	1RP-5365
Facility ID	
Application ID	pAB1904451625

Was this a major
release as defined by
19.15.29.7(A) NMAC?

If YES, for what reason(s) does the responsible party consider this a major release?

☐ Yes ☒ No

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Notice was provided via email to Kerry Fortner 02/08/19 10:30 AM

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.


If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name Thomas Haigood

Title: HSE Coordinator

Signature: 

Date: 02/08/19

email: Thomas.haigood@mavresources.com

Telephone: (432) 701-7802

OCD Only

Received by: 

Date: 2/13/2019