

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report



Name of Company: XTO Energy	Contact: Kyle Littrell	OGRID# 5380 <i>AB</i>
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331	
Facility Name: Poker Lake Unit #423H Battery (API for PLU #423H)	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No: 30-015-40710

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	19	25S	30E	1700	South	1030	East	Eddy

Latitude 32.112914° Longitude -103.915366° NAD83

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	35 bbls	Volume Recovered	35 bbls
Source of Release	Valve	Date and Hour of Occurrence	12/12/2017 time unknown	Date and Hour of Discovery	12/12/2017 9:15 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Crystal Weaver (NMOCD), Shelly Tucker/Jim Amos (BLM)		
By Whom?	Jacob Foust	Date and Hour:	12/12/2017 4:56 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* A 1/2" valve under the head switch located within the area of lined containment was discovered open. Valve was closed and facility was returned to production.					
Describe Area Affected and Cleanup Action Taken.* The release affected the impermeable containment liner. No fill material was located inside containment. A XTO EHS Coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified there was no visual evidence of a liner breach. All free-standing liquids were recovered from the containment and the containment and equipment were power washed.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Kyle Littrell		Approved by Environmental Specialist: Victoria Venegas 			
Title: Environmental Coordinator		Approval Date: 05/10/2019		Expiration Date:	
E-mail Address: Kyle.Littrell@xtoenergy.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 12/21/2017 Phone: 432-221-7331				2RP-5403	

* Attach Additional Sheets If Necessary

pAB1913053720
NAB1913054056