

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NAB1921736522
District RP	2RP-5549
Facility ID	
Application ID	pAB1921736242

## Release Notification

### Responsible Party

Responsible Party Read & Stevens, Inc.	OGRID 18917
Contact Name Kelly Barajas	Contact Telephone 575-624-3760
Contact email kbarajas@read-stevens.com	Incident # (assigned by OCD) NAB1921736522
Contact mailing address PO Box 1518, Roswell, NM 88202	

Latitude **32.320914** Longitude **-104.283364**  
**32-19-15.29N NAD 83** **104-17-00.11W**  
 (NAD 83 in decimal degrees to 5 decimal places)

Site Name Bandit State #1 SWD	Site Type SWD well
Date Release Discovered 7/16/2019	API# (if applicable) 30-015-21071

Unit Letter	Section	Township	Range	County
F	10	23S	26E	Eddy County, NM

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: \_\_\_\_\_)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 100	Volume Recovered (bbls) In Progress
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

There was a hole in the discharge line.


State of New Mexico  
Oil Conservation Division

Incident ID	NAB1921736522
District RP	2RP-5549
Facility ID	
Application ID	pAB1921736242

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? <b>There was a minimum of 100 bbls of water released from the hole in the discharge line.</b>
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? <b>By phone, spoke with Robert Hamlet at the OCD office for Eddy County at 11:45 AM on July 16, 2019. Followed up with 3 emails.</b>	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: <b>Joe Tovar is in contact with Republic Backhoe Service to find out when they are available to recover the water and contaminated soil from the release.</b>	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Kelly Barajas</u> Signature: <u></u> email: <u>kbarajas@read-stevens.com</u>	Title: <u>Production &amp; Regulatory</u> Date: <u>July 16, 2019</u> Telephone: <u>575-624-3760</u>
<b><u>OCD Only</u></b> Received by: <u>Amalia Bustamante</u> Date: <u>8/5/2019</u>	