Form C-141 Page 6

State of New Mexico Oil Conservation Division

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

Incident ID	
District RP	1RP-5358
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

A scaled site and sampling diagram as described in 19.15.29.11 N	NMAC	
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
■ Laboratory analyses of final sampling (Note: appropriate ODC D	ristrict office must be notified 2 days prior to final sampling)	
Description of remediation activities		
and regulations all operators are required to report and/or file certain remay endanger public health or the environment. The acceptance of a C should their operations have failed to adequately investigate and remed human health or the environment. In addition, OCD acceptance of a C compliance with any other federal, state, or local laws and/or regulation restore, reclaim, and re-vegetate the impacted surface area to the conditaccordance with 19.15.29.13 NMAC including notification to the OCD	C-141 report by the OCD does not relieve the operator of liability diate contamination that pose a threat to groundwater, surface water, 1-141 report does not relieve the operator of responsibility for ns. The responsible party acknowledges they must substantially tions that existed prior to the release or their final land use in 0 when reclamation and re-vegetation are complete. Title: HSE Coordinator	
OCD Only		
Received by: Victoria Venegas	Date: 09/20/2019	
	liability should their operations have failed to adequately investigate and ter, human health, or the environment nor does not relieve the responsible regulations. Date: 10/31/2019 Title: Engineering Tech.	