

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMNM120901

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. SND 12 01 FED 003 1H
2. Name of Operator CHEVRON USA INCORPORATED		9. API Well No. 30-015-45420-00-X1
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		10. Field and Pool or Exploratory Area WILDCAT
3b. Phone No. (include area code) Ph: 432-687-7665		11. County or Parish, State EDDY COUNTY, NM
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 12 T24S R31E SESE 367FSL 1210FEL 32.225639 N Lat, 103.726898 W Lon		

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Drilling Operations
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

- 5/6/19 - Test 13-3/8" surf csg to 1,920 psi for 30 min, good test.
- 7/13/19 - Full BOPE test to 250 psi low/6,650 psi high, all tests good.
- 7/15/19-7/17/19 - Drill 12-1/4" intermediate hole to 4,624'. Notified BLM of intent to run & cmt interm csg.
- 7/18/19 - Ran 9-5/8" 43.50#, L-80 LTC csg to 4,614'; float collar @ 4,534', float shoe @ 4,612'.
- 7/19/19 - Cemented csg in place w/ 988 sx, Class C cmt, 44 bbls of cmt to surface, full returns throughout job, TOC @ surface. WOC 24hrs from CIP per BLM requirements.

14. I hereby certify that the foregoing is true and correct.	
Electronic Submission #510041 verified by the BLM Well Information System For CHEVRON USA INCORPORATED, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 04/09/2020 (20PP1973SE)	
Name (Printed/Typed) LAURA BECERRA	Title REGULATORY SPECIALIST
Signature (Electronic Submission)	Date 04/07/2020

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By ACCEPTED	JONATHON SHEPARD Title PETROLEUM ENGINEER	Date 04/10/2020
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #510041 that would not fit on the form

32. Additional remarks, continued

7/20/19 - BOPE test to 250 psi low/6,650 psi high, all tests good. Test 9-5/8" interm csg to 2,342 psi for 30 min, good test. Begin drilling 8-1/2" prod csg hole.

7/23/19 - Perform loss circulation cement job, 296 sx, Class C cmt, 7,395'-8,395'.

7/25/19 - Continue drilling 8-12" prod csg hole from 7,395'.

8/7/19 - Notified BLM of intent to test BOPE. BOPE test to 250 psi low/6,650 psi high, all tests good.

8/9/19 - Continue drilling 8-12" prod csg hole from 16,043'.

8/11/19 - Reached TD 19,513'.

8/13/19 - Notified David Marvin @ BLM of intent to run & cement csg. Ran 5-1/2" 20#, P-110 BTC csg to 19,504'; float collar @ 19,460', float shoe @ 19,501'. PBD: 19,419'

8/16/19 - Cemented prod csg in place w/ 2,494 sx, Class C cmt, 0 bbls to surface, full returns throughout job. TOC: ~4,000'. WOC to reach 50 psi CS per BLM requirements.

8/17/19 - Released rig

1/21/20 - Pressure test liner to 11,350 psi for 30 min, good test.

Revisions to Operator-Submitted EC Data for Sundry Notice #510041

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	DRG SR	DRG SR
Lease:	NMNM120901	NMNM120901
Agreement:		
Operator:	CHEVRON USA INC 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432-687-7665	CHEVRON USA INCORPORATED 6301 DEAUVILLE BLVD MIDLAND, TX 79706 Ph: 432 687 7100
Admin Contact:	LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665	LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665
Tech Contact:	LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665	LAURA BECERRA REGULATORY SPECIALIST E-Mail: LBECERRA@CHEVRON.COM Ph: 432-687-7665
Location:		
State:	NM	NM
County:	EDDY	EDDY
Field/Pool:	WILDCAT	WILDCAT
Well/Facility:	SND 12 01 FED 003 1H Sec 12 T24S R31E Mer NMP SESE 367FSL 1210FEL	SND 12 01 FED 003 1H Sec 12 T24S R31E SESE 367FSL 1210FEL 32.225639 N Lat, 103.726898 W Lon