Form 3160-5 (June 2015)

OCD - REC'D 9/21/2020

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC048479A

SUNDRY NOTICES AND REPORTS ON WELLS

abandoned we	6. If Indian, Allottee	If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No. NMNM128925A			
SUBMIT IN	7. If Unit or CA/Agre NMNM128925				
Type of Well ☐ Gas Well ☐ Other Other			8. Well Name and No. ARTESIA YESO FEDERAL UNIT 26		
2. Name of Operator OXY USA WTP LP Contact: LESLIE REEVES E-Mail: LESLIE_REEVES@OXY.COM			9. API Well No. 30-015-41336-00-S1		
3a. Address 3b. Phone No		hone No. (include area code)		10. Field and Pool or Exploratory Area	
HOUSTON, TX 77210		713-497-2492	ARTESIA		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State		
Sec 21 T17S R28E NWNE 965FNL 1966FWL			EDDY COUNT	Y, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES) TO IN	DICATE NATURE OI	F NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
➤ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	▼ Temporarily Abandon		
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal		
PLAN FORWARD: TD-4940'; PBTD-3723'; Perfs: 1. Notify BLM/NMOCD of casi	S: 3994'-4729'; CIBP-3944' URRENT ECONOMIC ENVIRONORARILY ABANDONED STATU 3994'-4729'; CIBP-3944' sing integrity test 24 hours in adva	IS FOR ONE YEAR UN ance. est casing to 500# for 30	TIL 09/30/2021.	ESTS TO EXTEND	
	Accepted for recorded NM	OCD DS			
14. I hereby certify that the foregoing is Con Name(Printed/Typed) LESLIE R	Electronic Submission #528902 For OXY USA W nmitted to AFMSS for processing	/TP LP, sent to the Carls by PRISCILLA PEREZ or	sbad		
•					
Signature (Electronic S	Submission)	Date 09/04/20)20		
	THIS SPACE FOR FE	DERAL OR STATE (OFFICE USE		
_Approved By_JONATHON SHEPARD		TitlePETROLE	JM ENGINEER	Date 09/08/2020	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		rant or			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			willfully to make to any department or	agency of the United	

Revisions to Operator-Submitted EC Data for Sundry Notice #528902

Operator Submitted BLM Revised (AFMSS)

TA NOI TA NOI Sundry Type:

NMLC048479A NMLC048479A Lease:

Agreement: NMNM128925X NMNM128925A (NMNM128925A)

Operator: OXY USA WTP LP OXY USA WTP LP

PO 4294

HOUSTON, TX 77210 HOUSTON, TX 77210 Ph: 713-497-2492 Ph: 713.366.5360

LESLIE REEVES LESLIE REEVES Admin Contact:

REGULATORY ADVISOR E-Mail: LESLIE_REEVES@OXY.COM Cell: 281-733-0824 REGULATORY ADVISOR

E-Mail: LESLIE_REEVES@OXY.COM Cell: 281-733-0824 Ph: 713-497-2492

Ph: 713-497-2492

Tech Contact:

LESLIE REEVES REGULATORY ADVISOR E-Mail: LESLIE_REEVES@OXY.COM Cell: 281-733-0824

LESLIE REEVES REGULATORY ADVISOR E-Mail: LESLIE_REEVES@OXY.COM Cell: 281-733-0824 Ph: 713-497-2492 Ph: 713-497-2492

Location:

NM EDDY NM EDDY State: County: Field/Pool: ARTESIA GLORIETA YESO **ARTESIA**

ARTESIA YESO FEDERAL UNIT 26 Sec 20 T17S R28E Mer NMP NWNE 965FNL 1966FEL ARTESIA YESO FEDERAL UNIT 26 Well/Facility:

Sec 21 T17S R28E NWNE 965FNL 1966FWL

32.824569 N Lat, 104.195648 W Lon

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Temporary Abandonment of Wells

Definition: A temporarily abandoned well is a completion that is not capable of production in paying quantities, but which may have future value. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

- 1. TA status will be effective for a period of up to one year from the date of sundry approval and can be renewed annually thereafter per IM NM-2016-017.
- 2. A bridge plug (CIBP) must be installed 50 to 100 feet above any open perforations or open hole. The CIBP must be capped with either a minimum of 25 sacks of cement if placed with tubing or 35 feet of cement if placed with a bailer. The top of the cement must be verified by tagging.
- 3. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. If the well does not pass the casing integrity test, then the operator shall, within 30 days, submit a procedure to either repair the casing or to plug and abandon the well.
- 4. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 5. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if it is not isolated by a packer.
- 6. A bradenhead test must be conducted. If the test indicates a problem, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- 7. Submit a subsequent Sundry Notice (Form 3160-5) with the following information:
 - a. A well bore diagram with all perforations, CIBP's, and tops of cement on CIBP's.
 - b. A description of the temporary abandonment procedure.
 - c. A clear copy or the original of the pressure test chart.