

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SEP 30 2011

Form C-141
Revised October 10, 2003

NMOC D ARTESIA
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-20281

Release Notification and Corrective Action

NMLB 1128657788

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229/37	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Satellite G	Facility Type	Injection Line

Surface Owner	Federal	Mineral Owner		Lease No.	NMLC-028784B
---------------	---------	---------------	--	-----------	--------------

BKU #241

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	30	17S	30E					Eddy

Latitude 32 48.688 Longitude 104 00.683

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10bbls	Volume Recovered	0bbls
Source of Release	Injection line	Date and Hour of Occurrence	09/21/2011	Date and Hour of Discovery	09/21/2011 3:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The injection line at the headers had a leak due to corroded pipe. The faulty joint of pipe has been replaced with a new joint.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of produced water were released from the injection line at Satellite G. The release area measured 6' x 40' in the pasture. (The closest well location to this release is the BKU 241 API# 30-015-20281). Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOC D/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name:

Josh Russo

Title:

HSE Coordinator

E-mail Address:

jrusso@conchoresources.com

Date:

09/28/2011

Phone:

432-212-2399

OIL CONSERVATION DIVISION

Signed By *Mike Branch*
Approved by District Supervisor:

Approval Date OCT 13 2011

Expiration Date:

Conditions of Approval:

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:
11/13/2011

Attached ☐

* Attach Additional Sheets If Necessary

JRP-918