

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 15 2011

Form C-141
Revised October 10, 2003

NMOCD ARTESIA
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	F.U.N. State #1H	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	
		Lease No. (API#)	30-015-37879

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	30	26S	28E	800	North	330	East	Eddy

Latitude 32 01.143 Longitude 104 07.132

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	20bbls
Source of Release	Water tank	Date and Hour of Occurrence	10/26/2010	Date and Hour of Discovery	10/26/2010 6:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



The natural gas water pump did not start, causing the water tank to overflow. Had mechanic check pump. Removed valve handle on supply gas valve to prevent accidental adjustment.

Describe Area Affected and Cleanup Action Taken.*

Initially 20bbls was released from the water tank and we were able to recover all 20bbls with a vacuum truck. All fluid was contained inside the facility firewall which is lined with a 40mil plastic liner. The contaminated gravel has been removed and clean gravel has been added as necessary. The location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Josh Russo	Approval Date: NOV 15 2011	Expiration Date: N/A
Title: HSE Coordinator	Conditions of Approval: N/A	Attached <input type="checkbox"/>
E-mail Address: jrusso@conchoresources.com		
Date: 11/14/2011 Phone: 432-212-2399		

Attach Additional Sheets If Necessary

2RP-465