

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

APR 11 2012

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

Name of Company: Chesapeake Operating, Inc.		Contact: Bradley Blevins	
Address: 1616 West Bender, Hobbs, NM 88240		Telephone No.: (575) 391-1462. ext. 86424	
Facility Name: Brushy 12 Federal 1		Facility Type: Tank Battery	
Surface Owner:		Mineral Owner:	API No.: 3001525416

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	12	26S	29E	560	South	1980	West	Eddy

Latitude: N32° 03' 04.77"

Longitude: W103° 56' 18.66"

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 35-bbls	Volume Recovered: 5-bbls
Source of Release: Hot Oil Unit	Date and Hour of Occurrence: 3/27/12	Date and Hour of Discovery: 3/27/12 @ 16:00 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD; BLM	
By Whom? Bradley Blevins	Date and Hour: 3/27/12 @ 1600 hrs.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Depth to Groundwater: ~ 125 feet

Describe Cause of Problem and Remedial Action Taken.\* A hot oil unit caught fire releasing 35 bbls of oil with 5 bbls recovered.

Describe Area Affected and Cleanup Action Taken.\* Approximately 23,940 square feet of area was affected by the release of ± 35-bbls of oil. V ± 5-bbls of oil were recovered from the site. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area. Standing liquid was scraped up, blended and stock piled on location. Impacted material was placed on the contaminated caliche to prevent additional contamination of the area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Signed By: <i>M. L. Brannon</i>	
Title: EH & S Field Specialist		Approved by District Supervisor:	
E-mail Address: bradley.blevins@chk.com		Approval Date: APR 24 2012	Expiration Date:
Date: Phone: (575) 391- 1462, #86424		Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <i>5/24/2012</i>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2 RA - 1105