

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

APR 26 2012

Form C-141
Revised October 10, 2003

NMOC District Office in
Artesia, NM 88210
in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

264324

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: CA Russell #15	Facility Type: Oil

Surface Owner: Federal	Mineral Owner: Federal	API No.: 300158757
------------------------	------------------------	--------------------

LOCATION OF RELEASE

30-015-28757

Unit Letter F	Section 18	Township 17S	Range 31E	Feet from the 1500	North/South Line North	Feet from the 1950	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.8376298363716 Longitude: -103.910552975336

NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 4 / 2	Volume Recovered: 3 / 1
Source of Release: Poly- pipeline	Date and Hour of Occurrence: 04/16/2012 1pm	Date and Hour of Discovery: 04/16/2012 1:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston- BLM	
By Whom? Joe Hernandez	Date and Hour 04/17/2012 1pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Roustabout crew was walking lines and spot a clamp leaking on existing unknown contaminated area, crew removed clamp and fuse line back together, and used vac truck to recover fluid

Describe Area Affected and Cleanup Action Taken.* : Further remedial action pending...

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>[Signature]</u>	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Signed By <u>[Signature]</u> Approved by District Supervisor:	
Title: Production Foreman	Approval Date: MAY 23 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com Date: 04/26/2012 Phone: 575-942-9492	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>6/23/2012</u>	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-1125