

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1217341655

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Lime Rock Resources II-A, L.P. 271558	Contact	Michael Barrett
Address	1111 Bagby St Suite 4600 Houston, TX 77002	Telephone No.	575-623-8424
Facility Name	West Red Lake Unit #44	Facility Type	WIW

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-015-28444
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	5	18S	27E	840'	FSL	1750'	FWL	Eddy

Latitude 32.77161 Longitude 104.30283

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	49 bbls	Volume Recovered	12 bbls
Source of Release	2" Injection Line Split @ Wellhead	Date and Hour of Occurrence	06/07/2012 am	Date and Hour of Discovery	06/07/2012 @ 8 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher / NMOCD and Jim Amos / BLM via voicemail		
By Whom?	Michael Barrett	Date and Hour	6/8/12 @ 3 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
2" Injection Line Split @ Wellhead.
Shut off water flow, repaired line & bermed flow path.

Describe Area Affected and Cleanup Action Taken.*
Packed Caliche & Rock.
Talon LPE has been contracted to do site assessment and formulate a work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Michael Barrett

Printed Name: Michael Barrett

Title: Production Supervisor

E-mail Address: mbarrett@limerockresources.com

Date: 06/08/2012

Phone: 575-623-8424

OIL CONSERVATION DIVISION

Signed By *Mike Bratcher*

Approved by Environmental Specialist:

Approval Date: **JUN 21 2012** Expiration Date:

Conditions of Approval:

Attached ☐

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

7/21/12

* Attach Additional Sheets If Necessary

2RP-1183

RECEIVED
JUN 19 2012
NMOCD ARTESIA