

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1219350779 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P. <i>260737</i>	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name: Indian Flats Bass Federal #1 SWD	Facility Type: E&P

Surface Owner Federal	Mineral Owner Federal	Lease No. LC-067144 <i>API#</i>
-----------------------	-----------------------	---------------------------------

Indian Flats Bass Fed #1

LOCATION OF RELEASE

30-015-24968

Unit Letter J	Section 35	Township 21S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.433905 Longitude W 104.055425

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 50 bbls	Volume Recovered: 10 bbls
Source of Release: A SWD pump	Date and Hour of Occurrence 5/23/12 time unknown	Date and Hour of Discovery 5/23/12 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104	
By Whom? Tony Savoie	Date and Hour 5/23/12 1:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A 1" valve was left open on the pump causing the sump to overflow. The valve was closed.

Describe Area Affected and Cleanup Action Taken.* The released fluid affected approximately 8,000 sq. ft. area around the pump, lease road and caliche well pad. The free standing fluid was picked up with a vacuum truck and the saturated soil was scraped up and stockpiled on-site. The spill covered the same area as another spill reported on 2/8/12.

The Site remediation for the produced water will follow the NMOCD guidelines for leaks and spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by District Supervisor:	
Title: Waste Mgmt. & Remediation Specialist		Signed By <i>Mike B...</i>	
E-mail Address: TASavoie@BassPet.com		Approval Date: JUL 11 2012 Expiration Date:	
Date: 6/24/12 Phone: 432-556-8730		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/11/12

2RP-1208

