

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

JUN 26 2012

NMOCD ARTESIA

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
20 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1219343081

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company BOPCO, L.P.	260737	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220		Telephone No. 432-556-8730
Facility Name James Ranch Unit #36 Tank Battery		Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No NM-02884B
-----------------------	-----------------------	--------------------

LOCATION OF RELEASE

30-015-27686

Unit Letter NG	Section 361	Township 22S 23S	Range 30E	Feet from the 1980	North/South Line North	Feet from the 1860	East/West Line East	County Eddy
-------------------	----------------	------------------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.335615 Longitude W 103.832117

NATURE OF RELEASE

Type of Release: Produced water and crude oil	Volume of Release: 450 bbls of produced water and 5 bbls of crude oil.	Volume Recovered: 100 bbls produced water.
Source of Release: Produced water storage tank	Date and Hour of Occurrence 6/24/12, Hour unknown	Date and Hour of Discovery 6/24/12 7:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Emergency #104 and Jim Amos with the BLM	
By Whom? Tony Savoie	Date and Hour 6/24/12, NMOCD at 9:14 a.m. BLM at 9:37 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* The primary water pump failed to operate properly due to motor bearing problems, the secondary water transfer pump failed to operate due to Head Switch malfunction, the high level alarm failed to operate properly due to a calibration error and wiring problem. All failures were corrected the same day.

Describe Area Affected and Cleanup Action Taken. Approximately 32,900 sq.ft. of caliche road and tank battery pad area around the JRU-36 and the road going to the Hudson Federal and adjacent well pad. Approximately 800 sq.ft. of pasture land was impacted near the Hudson tank battery. The tank battery location at the JRU-36 was currently being re-built and remediated; approximately 340 cubic yards of impacted soil had been excavated and hauled to Lea Land. The area around the tanks had been sampled on 6/13/12 to determine the amount of contamination that remained around the tank battery and the vertical extent of the historical releases. A copy of the sample results is attached. Vertical extent could not be obtained during the sampling event, an air rotary rig was being scheduled to complete the delineation. We will continue to delineate the area around the tank battery and the newly impacted area from the recent release. A remediation plan will be developed in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signatures: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by District Supervisor:	Signed By: M. H. [Signature]
Title: Waste Mgmt. & Remediation Specialist	Approval Date: JUL 11 2012	Expiration Date:
E-mail Address: TASavoie@BassPet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/24/12	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8-11-2012

2RP-1204