## **Permit Comments**

**Operator: YATES PETROLEUM CORPORATION, 25575** 

Well:

**STADIUM STATE UNIT #001** 

$\circ$							127			$c \circ$	
` ≺	(')	~	$\sim$	<i>ભ</i> ડ	~	- 1	/	つし	`	. –	
	$\sim$		$\sim$				ح.				

User Name	Comment	Comment Date		
BASHER	Sources at Yates Petroleum Corporation have relayed information to me that they believe there will not be enough H2S found from the surface through the Precambrian formation to meet the OCD's minimum requirements for the submission of a contingency plan per Rule 118.			
BASHER	Any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines with approved general permit on file.	5/6/2005		
BASHER	The State Engineers Web Site has been accessed for the captioned well. The depth to ground water is approximately 124', the distance from the nearest fresh water well is approximately 21,000' and the distance from the nearest surface water is approximately 800'. With this information obtained from the web site the Site Ranking for this well is 10 points. With this ranking score deep trench burial and capping will take place at pit closure.	5/6/2005		