Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources		Form C-103 May 27, 2004 WELL API NO.
1301 11. Grand 1110., 1110.312, 1111. 002.10	ONSERVATION DIVISION 20 South St. Francis Dr. Santa Fe, NM 87505	30-015-20358 5. Indicate Type of Lease STATE ☐ FEE ☒ 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND RE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR. USE "APPLICATION FOR PER PROPOSALS.) 1. Type of Well: Oil Well Gas Well 3. Name of Operator Yates Petroleum Corporation 3. Address of Operator 105 S. 4th Street, Artesia, NM 88210 4. Well Location	OR TO DEEPEN OR PLUG BACK TO A RMIT" (FORM C-101) FOR SUCH Other P&A RECEIVED MAR 2 4 2005	7. Lease Name or Unit Agreement Name Brown Yates 8. Well Number 1 9. OGRID Number 025575 10. Pool name or Wildcat Penasco Draw SA-Yeso Assoc.
Unit Letter I : 1650 feet from the South line and 990 feet from the East line Section 24 Township 18S Range 25E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3451'GR Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grae	de Tank: Volumebbls; Co	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS.☐ PLUG AND ABANDON ☐ CASING/CEMENT JOB ☐		
OTHER:	☐ OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
3/14/05 – Began P&A procedures. 3/15/05 – POOH with 2-3/8" tubing. Set CIBP at 1417'. Circulated with 10# mud. Perforated at 1276'. OCD approved perforation and test instead of CBL. Tested to 500#. Spotted 35 sx cement at 1417'. 3/16/04 – Tagged at 1128'. Perforated at 578'. Tested to 500#. Spotted 30 sx cement at 628'. WOC. Tagged at 335'. Spotted 15 sx at 60' to surface. Installed dry hole marker. FINAL REPORT. WELL IS PLUGGED AND ABANDONED.		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.		
SIGNATURE (ma) (menta)	TITLE Regulatory.Complia	proce-Supervisor DATE March 21, 2005
Type or print name Tina Huerta	E-mail address: <u>tinah@ypcnm.c</u>	050
For State Use Only APPROVED BY: Conditions of Approval (if any):	TITLE	SEP 1 3 2005