

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 29 2012

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1234247553

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 29 State Com #3H	Facility Type	Well location

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-39404
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	29	25S	28E					Eddy

Latitude 32 05.669 Longitude 104 06.699

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	12bbls	Volume Recovered	10bbls
Source of Release	Storage tank	Date and Hour of Occurrence	11/17/2012	Date and Hour of Discovery	11/17/2012 7:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A 2" valve was left open on a storage tank which allowed the release of fluid. The valve has been sealed to prevent reoccurrence.

Describe Area Affected and Cleanup Action Taken.*

Initially 12bbls of produced water were released from the storage tank and we were able to recover 10bbls with a vacuum truck. The release occurred at the southwest edge of the pad adjacent to the lease road entering the well location. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Approved by District Supervisor: Signed By 	
Title: Senior Environmental Coordinator		Approval Date: JEC 07 2012 Expiration Date:	
E-mail Address: jrusso@concho.com		Conditions of Approval: Attached <input type="checkbox"/>	
Date: 11/29/2012 Phone: 432-212-2399			

* Attach Additional Sheets If Necessary

2RP-1435

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

Jan. 7th 2013