

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 28 2012

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1234241521

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy 162683	Contact	Terry D. Ainsworth
Address	600 Marienfeld Midland, TX 79701	Telephone No.	(575) 390-1388
Facility Name	Gadwall 18 FC 3	Facility Type	oil well

Surface Owner	Mineral Owner	Lease No.	NM 2575
---------------	---------------	-----------	---------

LOCATION OF RELEASE

API: 30-015-39964

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	18	25S	27E	330	North	810	West	Eddy

Latitude N 32°08' 10.680" Longitude W 104°14' 06.052"

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	120 bbls	Volume Recovered	55 bbls
Source of Release	Illegal dumping	Date and Hour of Occurrence	11/23/2012 PM	Date and Hour of Discovery	11/24/2012 1:00 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Email to Terry Gregston and Mike Bratcher		
By Whom?	Terry D. Ainsworth	Date and Hour	11/24/2012 3:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The pumper, Justin Reeves arrived on location Sunday morning and found what looked like someone unloaded a load of produced water.

Justin Reeves 575 390 8564

Describe Area Affected and Cleanup Action Taken.*

The illegal dump was found on the NW corner of the location. We fenced it off to keep the cattle out. SESI is lined out to make the one call and come out and catch samples. I will let BLM and NMOCD know when we get this scheduled. Area is approximately 40' x 25'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Terry D. Ainsworth

Approved by District Supervisor:

Signed By M. L. Bratcher

Title: Senior Production Foreman

DEC 07 2012

Approval Date:

Expiration Date:

E-mail Address: tainsworth@cimarex.com

Conditions of Approval:

Attached ☐

Date: 11/24/2012

Phone: 575-390-1388

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

January 7th 2013

2RP-1434