

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 08 2013

Form C-141  
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC

NMOCD ARTESIA

### Release Notification and Corrective Action

JMW 1301735558

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Jose Hernandez
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739
Facility Name: Skelly 401		Facility Type: Oil Well



Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001529817
------------------------	------------------------	---------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	28	17S	31E	1300	North	60	West	Eddy

Latitude: 32.8092438074323 Longitude: -103.883084059221

### NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 6 bbls / 1 bbl	Volume Recovered: 4 bbls / 0
Source of Release: 3" polyline	Date and Hour of Occurrence: 12/23/2012 9am	Date and Hour of Discovery: 12/23/2012 9:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher - NM OCD Terry Gregston- BLM	
By Whom? Gary Wink	Date and Hour 01/04/2013 9:15am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: cause of leak, scale in 3" poly line		
Describe Area Affected and Cleanup Action Taken.*: Spill is about 8 ft wide at widest point with a trail that's is about 1ft wide to a small puddle that is about 3ftX4ft all together spill is about 8ftX50ft		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Jose Hernandez	Approved by District Supervisor:	Signed By 
Title: Production Foreman	Approval Date: JAN 17 2013	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/07/2013 Phone: 575-942-9492		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL NOT LATER THAN:

February 17<sup>th</sup> 2013

2RP-1500