


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NJMW1301853525

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chevron USA 241333	Contact: Amy Barnhill
Address: 2401 Avenue O Eunice, NM 88231	Telephone No.: 432-940-8524
Facility Name: Catclaw Draw Unit #18	Facility Type: Tank Battery

Surface Owner: State of NM	Mineral Owner: State of NM	API No. 30-015-33320
----------------------------	----------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	23	21-S	25-E		1310		1310	Eddy

Latitude: 32.46832 Longitude: -104.36972

NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release: 2.951	Volume Recovered: 5bbls
Source of Release: Tank Valve	Date and Hour of Occurrence: 12-2-2012	Date and Hour of Discovery: 12-2-2012 @ 11:48am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Called 575-393-6161 E.L. Gonzales	
By Whom? Amy Barnhill	Date and Hour: 12-3-2012 @ 2:48pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A ball valve in the back of the tank has a hole in it. F.S. found the leak at 11:48 am. He immediately plugged the valve and called a vacuum truck

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck picked up a total of 5 bbls fluid and 2.951 bbls soaked into the gravel. Further remediation will be performed in accordance with a NMOCD approved remediation plan.

Total spill volume was 7.951 Bbls, 4.77 water and 3.18 oil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Amy Barnhill		Approved by Environmental Specialist: Signed By <i>Mike Barnhill</i>	
Title: HE Specialist		Approval Date: JAN 18 2013	Expiration Date:
E-mail Address: ABarnhill@chevron.com		Conditions of Approval:	
Date: 12-3-2012 Phone: 432-940-8524		Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: February 18 2013	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1507