


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMW 1302240439

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ West Coop #210	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	Lease No. (API#) 30-015-36703
---------------	-------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	16	17S	29E					Eddy

Latitude 32 50.334 Longitude 104 04.994

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	4bbls Oil 6bbls Produced water	Volume Recovered	3bbls Oil 5bbls Produced water
Source of Release	Fire tube gasket	Date and Hour of Occurrence	01/03/2013	Date and Hour of Discovery	01/03/2013 9:30 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

There was a fire tube gasket failure on the heater treater inside the facility. The heater treater has been drained and the fire tube has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of produced fluids were released and we were able to recover 8bbls with a vacuum truck. The release was completely contained inside the lined facility. All free fluid has been recovered and contaminated gravel has been removed. Fresh gravel has been added to the facility as needed. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	Signed By
Title:	Senior Environmental Coordinator	Approval Date:	JAN 22 2013
E-mail Address:	jrusso@concho.com	Expiration Date:	
Date:	01/15/2013	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>
		Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	

PROPOSAL NO LATER THAN:
February 22, 2013

2 RP-1512

* Attach Additional Sheets If Necessary