


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company **COG OPERATING LLC 217955** Contact **Pat Ellis**
Address **600 West Illinois Avenue, Midland, TX 79701** Telephone No. **432-230-0077**
Facility Name **Mongo 25 Federal Com #2** Facility Type **Tank Battery**

Surface Owner **Federal** Mineral Owner Lease No. (API#) **30-015-37164**

LOCATION OF RELEASE

Unit Letter H	Section 25	Township 24S	Range 28E	Feet from the 	North/South Line 	Feet from the 	East/West Line 	County Eddy
-------------------------	----------------------	------------------------	---------------------	--------------------------	-----------------------------	--------------------------	---------------------------	-----------------------

Latitude **32.19034** Longitude **104.03323**

NATURE OF RELEASE

Type of Release Oil and Produced water	Volume of Release 45bbls Oil 5bbls Produced water	Volume Recovered 44bbls Oil 4bbls Produced water
Source of Release Oil and Produced water tanks	Date and Hour of Occurrence 12/31/2012	Date and Hour of Discovery 12/31/2012 7:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-OCD	
By Whom? Michelle Mullins	Date and Hour 01/05/2013	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Two small holes were found in the side of the oil tank and one small hole was found in the produced water tank inside the Mongo 25 Federal Com #2 Tank Battery allowing the release of fluid. The tanks will be repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 50bbls of produced fluid were released and we were able to recover 48bbls with a vacuum truck. All fluid that was released was contained inside the lined facility. All free fluid has been recovered and the tanks have been cleaned. Stained gravel has been removed from the facility and replaced with fresh gravel as needed. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: **Josh Russo**

Title: **Senior Environmental Coordinator**

E-mail Address: **jrusso@concho.com**

Date: **01/15/2013** Phone: **432-212-2399**

Approved by District Supervisor: Signed By

Approval Date: **JAN 22 2013**

Expiration Date:

Conditions of Approval:

Attached ☐

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**

February 22, 2013

2RP-1513

* Attach Additional Sheets If Necessary