

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

OCT 01 2012

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Name of Company Chevron USA Inc. 4323		Contact David A. Pagano	
Address 15 Smith Rd., Midland, TX, 79705		Telephone No. wk: 575-396-4414X275 cell: 505-787-9816	
Facility Name Skelly 907 BTY		Facility Type Oil Production Batteries	
Surface Owner Federal BLM		Mineral Owner Federal API No. 30-015-31385	


SKU 907 BTY (CTB) - Latitude: 32.819634 / Longitude: -103.872881

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	22	17S	31E					Eddy

21 17 31

NATURE OF RELEASE

Type of Release Gases to a Flare	Volume of Release 300 MSCF	Volume Recovered 0 MSCF
Source of Release Flare	Date and Hour of Occurrence 09/23/12 09:00 AM	Date and Hour of Discovery 09/23/12 09:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bratcher, Mike, EMNRD	
By Whom?	Date and Hour 09/24/12 08:30 AM left voicemail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* High Line Pressure to Frontier Gas Sales Line.		
Describe Area Affected and Cleanup Action Taken.* Shut in wells to minimize flaring.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: David A. Pagano		Approved by Environmental Specialist: Accepted for record NMOCD
Title: Health & Environmental Specialist		Approval Date: _____ Expiration Date: _____
E-mail Address: dpgn@chevron.com		Conditions of Approval: _____ Attached <input type="checkbox"/>
Date: 10/01/12 Phone: 505-787-9816		

* Attach Additional Sheets If Necessary

2RP-1553