



District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Appropriate District Office in  
accordance with 19.15.29 NMAC

**Release Notification and Corrective Action**

*njmwl305850658* OPERATOR  Initial Report  Final Report

Name of Company: Linn Operating *269324* Contact: Joe Hernandez  
 Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739  
 Facility Name: J.L. Keel B 39 Facility Type: Injection P&A

Surface Owner: Federal Mineral Owner: Federal API No.: 3001525920

**LOCATION OF RELEASE**

Unit Letter M	Section 05	Township 17S	Range 31E	Feet from the 510	North/South Line South	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.85764 Longitude: -103.89745

**NATURE OF RELEASE**

Type of Release: Produced Water / Oil	Volume of Release: 9bbls / 1bbl	Volume Recovered: 5bbls / 0
Source of Release: Pipeline FG	Date and Hour of Occurrence: 01/24/2013 9am	Date and Hour of Discovery: 01/24/2013 9:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 01/25/2013 9:45am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Furgesson construction was excavating for new pipeline. At this time they hit a 2" Fiberglass injection line. The line was under pressure but was originally feeding Keel B #39, a plugged and abandoned well. Line was shut in and vacuum truck was called. Vacuum truck picked up approximately 5BBL.

Describe Area Affected and Cleanup Action Taken.\*: Area affected was inside ditch from pipeline excavation. It covered an area 4' by 30'. Leak site was approximately 80' from dry hole marker.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jose Hernandez</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jose Hernandez	Approved by District Supervisor: <i>Mike Hernandez</i>	Signed By: <i>Mike Hernandez</i>
Title: Production Foreman	Approval Date: <b>FEB 27 2013</b>	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval: Remediation per OCD Rule &	Attached <input type="checkbox"/>
Date: 02/26/2013 Phone: 575-942-9492		

\* Attach Additional Sheets If Necessary

**GUIDELINES. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: March 27, 2013**

*2RP-1570*