

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAR 05 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

JM 1306550.350 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	DODD FEDERAL UNIT #15A	Facility Type	TANK BATTERY
Dodd Fed. Unit #110			
Surface Owner	FEDERAL	Mineral Owner	
		Lease No. (API#)	30-015-35139


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	17S	29E					EDDY

Latitude 32.82827

Longitude 104.05744

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	100bbls	Volume Recovered	99bbls
Source of Release	Open valve on tank	Date and Hour of Occurrence	02-24-2013	Date and Hour of Discovery	02-24-2013 6:55am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jim Amos - BLM / Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	02-25-2013 9:17am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Due to a closed equalizer line the oil tank at the facility overflowed. We have opened the equalizer line to prevent reoccurrence.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 100bbls of oil were released from the oil tank inside the tank battery due to a closed equalizing line. We were able to recover 99bbls of oil with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Approved by District Supervisor:		Accepted for record NMOCD	
Title: Senior Environmental Coordinator		Approval Date: MAR 06 2013		Expiration Date:	
E-mail Address: jrusso@concho.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 03-04-2013 Phone: 432-212-2399					

* Attach Additional Sheets If Necessary

229-1577

Accepted for record
NMOCD