


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NTM 1306548/82

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Chevron USA 4323	Contact: Bradley Blevins
Address: P.O. Box 190, Hobbs, NM 88240	Telephone No.: (575) 391-1462 ext. 86424
Facility Name: Ross Ranch 6 Federal #1H	Facility Type: Pipeline
Surface Owner: BLM	Mineral Owner:
API No.: 30-015-36883	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	6	26S	30E	350	South	1880	East	Eddy

Latitude: N 32° 03' 55.15" Longitude: W 103° 55' 08.57"

NATURE OF RELEASE

Type of Release: Water and Oil	Volume of Release: 7.21 bbls	Volume Recovered: 0 bbls
Source of Release: open ended line	Date and Hour of Occurrence: 2/24/13 @ 1300 hrs	Date and Hour of Discovery: 2/24/13 @ 1300 hrs
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, EMNRD; Jim Amos, BLM	
By Whom? Bradley Blevins	Date and Hour: 2/24/13 @ 1728 hrs	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	
Depth to water: ~160 ft		
If a Watercourse was Impacted, Describe Fully:		
Describe Cause of Problem and Remedial Action Taken.* Release was caused by an open ended line. Approximately 6.71 bbls of water and 0.50 bbls of oil were released with 0 bbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area.		
Describe Area Affected and Cleanup Action Taken.* Visibly stained soil was excavated and hauled away for disposal at a state approved facility. Soil samples were collected and submitted to Cardinal Laboratories for testing. Upon receiving acceptable results and NMOC D approval, the affected area will be backfilled, and returned to proper conditions.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor:	
Title: HE Specialist	Approval Date: MAR 06 2013	Expiration Date:
E-mail Address: bradley.blevins@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-9-13 Phone: (575) 391-1462 ext. 86424		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:
April 6, 2013

2RP-1576