


State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

John Bemis
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

Jami Bailey
Division Director
Oil Conservation Division



Response Required - Deadline Enclosed

Underground Injection Control Program

"Protecting Our Underground Sources of Drinking Water"

19-Mar-13

COG OPERATING LLC
ONE CONCHO CENTER
600 W. ILLINOIS AVE
MIDLAND TX 79701

LETTER OF VIOLATION and SHUT-IN DIRECTIVE
Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

DODD FEDERAL UNIT No.027

Test Date: 3/18/2013
Test Reason: 5-year Test
Test Type: Std. Annulus Pres. Test
Comments on MIT: Well will not hold pressure

Active Injection - (All Types)
Permitted Injection PSI:
Test Result: F
FAIL TYPE: Other Internal Failure

30-015-02978-00-00

C-14-17S-29E

Actual PSI: 0
Repair Due: 6/21/2013
FAIL CAUSE:

RJ UNIT No.119

Test Date: 3/18/2013
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Operator reports well will not pass an mit test. Test not run.

Active Injection - (All Types)
Permitted Injection PSI:
Test Result: F
FAIL TYPE: Other Internal Failure

30-015-03146-00-00

O-27-17S-29E

Actual PSI:
Repair Due: 6/21/2013
FAIL CAUSE:

G J WEST COOP UNIT No.001

Test Date: 3/18/2013
Test Reason: Annual IMIT
Test Type: Bradenhead Test
Comments on MIT: Operator reports well will not pass

Active Injection - (All Types)
Permitted Injection PSI:
Test Result: F
FAIL TYPE: Other Internal Failure

30-015-03176-00-00

M-28-17S-29E

Actual PSI:
Repair Due: 6/21/2013
FAIL CAUSE:

March 20, 2013

Page 2

NEW MEXICO E O STATE COM No.001

30-015-25077-00-00

E-20-17S-29E

Active Salt Water Disposal Well

Test Date: 3/19/2013

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 6/22/2013

Test Type: Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Blow of fluid from casing. Hooked up truck to bleed off, shut in valve and already had fluid when re-

OXY SPUMONI STATE No.001

30-015-33089-00-00

P-16-17S-31E

Active Salt Water Disposal Well

Test Date: 3/18/2013

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 6/21/2013

Test Type: Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Operator reports well will not pass test. Test not run.

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of **CIVIL PENALTIES** for your violation of OCD rules.

Sincerely,

Richard [Signature]
Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.