


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJM/W 310234975 OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	BURCH KEELY UNIT "E" (232)	Facility Type	TANK BATTERY

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-015-27992
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	23	17S	29E					EDDY

Latitude 32 48.800 Longitude 104 02.740

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	10bbls oil Produced water 20bbls	Volume Recovered	10bbls oil 19bbls Produced water
Source of Release	Gasket between fire tube and heater.	Date and Hour of Occurrence	03-24-2013	Date and Hour of Discovery	03-24-2013 9:16am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	03-25-2013 10:47am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A leak in the gasket between the fire tube and the heater. Replaced the gasket between the fire tube and the heater.

Describe Area Affected and Cleanup Action Taken.*

Initially 10bbls of oil and 20bbls of produced water were released from a leak that developed between the fire tube and the heater. We were able to recover 10bbls of oil and 19bbls of produced water with a vacuum truck. The release was completely contained inside the lined facility walls of the tank battery. All free fluid has been recovered. Any contaminated gravel has been removed and we have replaced with fresh gravel as necessary. The facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	Senior Environmental Coordinator	Approval Date:	Expiration Date:
E-mail Address:	jrusso@concho.com	Conditions of Approval:	
Date:	4-3-2013	Phone:	432-212-2399

2RP-16/6

* Attach Additional Sheets If Necessary

Accepted for record
NMOCD