

District I
1625 N. French Dr., Hobbs, NM 88240
District II
8145 First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 308551933 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Americo Energy Resources 228051	Contact Glenn Bertrand
Address 7575 San Felipe, Ste 200	Telephone No. 713-984-9700
Facility Name East Shugart	Facility Type Tank Battery

Surface Owner	Mineral Owner	API No. 30-015-27949 *
---------------	---------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	35	18S	31E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil	Volume of Release 200 +/-	Volume Recovered 200+/-
Source of Release Tank over flow	Date and Hour of Occurrence 3/13/13 @ ??	Date and Hour of Discovery 3/13/13 @ 9am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Artesia Office	
By Whom? Louis Edgett	Date and Hour 3/13/13 n/a	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

MAR 14 2013



Describe Cause of Problem and Remedial Action Taken.*

Production separator water dump malfunction allowing water to exit vessel with oil product to the sales oil tank/s which filled; over flowing into our secondary containment area. A small amount ran over to the immediate area next to our secondary containment but stayed within our facility boundary.

Describe Area Affected and Cleanup Action Taken.*

Water dump was fixed and vacuum trucks were immediately brought in to recover all available product back to our oil storage tank/s. Once free liquid is picked up the area will be remediated as per requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Glenn Bertrand	Approved by Environmental Specialist	Signed By 
Title: Operations Manager	Approval Date: MAR 26 2013	Expiration Date:
E-mail Address: glenn.bertrand@americoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/13/13 Phone: 713-984-9700	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

APRIL 26, 2013

2RP-1587