Submit 3 Copies To Appropriate District Office <u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico Energy, Minerals and Natural Resources	Form C-103 June 19, 2008 WELL API NO.
District IIOIL CONSERVATION DIVISION1301 W. Grand Ave., Artesia, NM 882101220 South St. Francis Dr.	30-015-00300 5. Indicate Type of Lease STATE ☐ FEE ⊠
1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505District IVSanta Fe, NM 875051220 S. St. Francis Dr., Santa Fe, NM87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A. DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name ATOKA SAN ANDRES UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other: <u>Water Injection Well</u>	8. Well Number #101
2. Name of Operator LIME ROCK RESOURCES II-A, L.P. RECEIVED	9. OGRID Number 277558
3. Address of Operator c/o Mike Pippin LLC, 3104 N. Sullivan, Farmington, NM 87401 MAY 15 2013	10. Pool name or Wildcat: Atoka, San Andres (03610)
4. Well Location MMOCD ARTESIA Unit Letter: C. : 990 feet from the <u>NORTH</u> line and <u>2310</u>	feet from the <u>WEST</u> line
Section 11. Township 18-S Range 26-E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc 3320' GL	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 🕴 REMEDIAL WOP	ILLING OPNS.
OTHER: OTHER: Locatio	n is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Op	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been \overrightarrow{A} steel marker at least 4" in diameter and at least 4' above ground level has been set	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, Q	UARTER/QUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATI PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	<u>ON HAS BEEN WELDED OR</u>
The location has been leveled as nearly as possible to original ground contour and has	been cleared of all junk, trash, flow lines and
other production equipment. \square Anchors, dead men, tie downs and risers have been cut off at least two feet below gro	und level.
If this is a one-well lease or last remaining well on lease, the battery and pit location	s) have been remediated in compliance with
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, pro from lease and well location.	duction equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been rem	oved. (Poured onsite concrete bases do not have
to be removed.) All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAG	C. All fluids have been removed from non-
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles a	nd lines have been removed from lease and well
location, except for utility's distribution infrastructure.	
I hereby certify that the information above is true and complete to the best of my knowled	ge and belief.
SIGNATURE Mike Pipping TITLE Petroleum Engineer - Ag	ent DATE 5/15/13
Type or print name <u>Mike Pippin</u> E-mail address: <u>mike@pippin</u> For State Use Only	llc.com PHONE: <u>505-327-4573</u>
KINDO L- FS. M.	
APPROVED BY:	Ursa DATE May 16-2013

OK	To	Release	0
		:	