

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NJM W1314038799*

**OPERATOR**

Initial Report  Final Report

Name of Company Mesquite SWD Inc. <i>161968</i>	Contact Clay L Wilson
Address P.O. 1479 Carlsbad NM 88221	Telephone No. 575 706 1840
Facility Name Big Eddy	Facility Type SWD Unload Station

Surface Owner Blm/ Creamer	Mineral Owner	API No.30-015=05819
----------------------------	---------------	---------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	3	20S	31E	660	FSL	660	FEL	

Latitude *32.597007* Longitude *103.850615*

**NATURE OF RELEASE**

Type of Release Produced water	Volume of Release 30bbls	Volume Recovered 15bbls
Source of Release Hole in flow line	Date and Hour of Occurrence 3/11/13 11.00am	Date and Hour of Discovery 3/11/13 11.00am
Was Immediate Notice Given? Required <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
*[Redacted]*

**RECEIVED**  
MAY 14 2013  
NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.\*  
Poly line looked like it rub up against something while being installed. In the process of digging out the contaminated soil and hauling it to CRI

Describe Area Affected and Cleanup Action Taken.\*  
Ranch Land, Digging out contaminated and hauling to CRI

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Clay Wilson*  
Printed Name: Clay L Wilson  
Title: President  
E-mail Address: Claywilson@hotmail.com  
Date: 5-13-13 Phone: 575 706 1840

**OIL CONSERVATION DIVISION**  
Approved by Environmental Specialist:  
Signed By: *Mike Benjamin*  
**MAY 20 2013**  
Approval Date: Expiration Date:  
Conditions of Approval:  
Remediation per OCD Rule &  
Guidelines. **SUBMIT REMEDIATION**  
Attached

\* Attach Additional Sheets If Necessary

**PROPOSAL NO LATER THAN:**  
June 20, 2013  
*2RP-1652*