

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 06 2013

Form C-141
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1315836886
Name of Company Oxy Permian Ltd. 16696
Address 1017 W. Stanolind Rd, Hobbs, NM
Facility Name Sand Dunes 28 Federal #1 SWD
Contact CJ Summers
Telephone No. (575) 397-8216
Facility Type SWD
Surface Owner BLM Mineral Owner Lease No. NM 40659

☒ Initial Report ☐ Final Report

LOCATION OF RELEASE

30-015-26194

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E					Eddy

Latitude N 32.27641° Longitude W 103.78047°

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 300 bbls	Volume Recovered 0 bbls
Source of Release Power failure/ Tank overflow	Date and Hour of Occurrence 04/22/2013	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? James Amos-BLM and Mike Bratcher-OCD	
By Whom? Chancey Summers	Date and Hour 04/22/2013 @ 11:03 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A power failure at the site caused 300 bbls of produced water to leak onto the ground. No fluids were recovered and the power was restored to the site.

Describe Area Affected and Cleanup Action Taken.*

The area affected is 400' x 100'. A power failure at the site caused 300 bbls of produced water to leak onto the ground. No fluids were recovered and the power was restored to the site. Remediation will be performed in accordance with an approved plan from the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by District Supervisor:	Signed By: 
Title: HES Specialist	Approval Date: JUN 07 2013	Expiration Date:
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/06/2013 Phone: (575) 397-8216		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

July 7, 2013

2RP-1678

Include API #

Please use updated Form