

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NTM 1317034502 Energy OPERATOR ☒ Initial Report ☐ Final Report

Name of Company DEVON ENERGY 6137	Contact DAN SUNIGA	
Address PO BOX 250 ARTESIA NM 88211	Telephone No. 575-746-5555	
Facility Name TODD 24 FED 2 BATTERY	Facility Type OIL WELL	
Surface Owner	Mineral Owner	API No. 3001527691

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	23S	31E	660'	North	1980"	East	Eddy

Latitude: 32.2952956145063 Longitude: -103.7294101096522

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 35bbls	Volume Recovered 30bbls
Source of Release Spill	Date and Hour of Occurrence June 12, 2013	Date and Hour of Discovery June 12, 2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/OCD, Jennifer Van Curen/BLM	
By Whom? Wesley Ryan	Date and Hour: June 13, 2013 8:15am/8:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

At the Todd 24 Fed 2 Battery, a transfer pumps discharge line plugged off from a slug of paraffin causing a produced water tank to run over resulting in a spill of 35 bbls of produced water.

Describe Area Affected and Cleanup Action Taken.*

The lease operator arrived to discover the produced water tank running over. The operator discovered that a slug of paraffin had built up in a 90 on the discharge side of the pump. The pump was unable to transfer the produced water off location and the tank filled up and ran over. The spill was estimated to be 35bbls of produced water within the containment around the tanks. A vacuum truck was dispatched and the driver recovered 30bbls. The operator then notified the Asst. Foreman and made arrangements to have the line cleaned, replace the pump and remove the contaminated soil around the tank. Also, the spill was contained within the unlined containment on the caliche pad.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Veronica Teel</i>	OIL CONSERVATION DIVISION	
Printed Name: Veronica Teel	Approved by Environmental Specialist: <i>Mike Bratcher</i>	Signed By: <i>Mike Bratcher</i>
Title: Field Admin Support	Approval Date: JUN 19 2013	Expiration Date:
E-mail Address: Veronica.Teel@dmv.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: June 14, 2013 Phone: 575-748-9933		

Attach Additional Sheets If Necessary

JULY 19, 2013

2RP-1686