

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 21 2013

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

NMOCD ARTESIA

Release Notification and Corrective Action

JMW 1318336125

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SKELLY UNIT #989	Facility Type	TANK BATTERY

Surface Owner	FEDERAL	Mineral Owner		Lease No. (API#)	30-015-36498
---------------	---------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	23	17S	31E					EDDY

Latitude 32.82191

Longitude 103.84353

NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 20bbls of oil 100bbls of produced water	Volume Recovered 20bbls of oil 95bbls of produced water
Source of Release Water tank	Date and Hour of Occurrence 06-08-2013	Date and Hour of Discovery 06-08-2013 4:45am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? James Amos - BLM / Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 06-08-2013 8:53PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A power outage occurred at the lease causing the KO to dump everything into the water tank. Restored power and reset equipment.

Describe Area Affected and Cleanup Action Taken.*

Initially 20bbls of oil and 100bbls of produced water were released from the produced water tank due to a power outage. We were able to recover 20bbls of oil and 95bbls of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluids have been recovered. Any contaminated gravel has been removed, the liner has been washed, and we have replaced with clean gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	<i>Robert Grubbs Jr.</i>
Printed Name:	Robert Grubbs Jr.
Title:	Senior Environmental Coordinator
E-mail Address:	rgrubbs@concho.com
Date:	06-21-2103
Phone:	432-661-6601

Approved by District Supervisor	Signed By <i>Mike Bratcher</i>
Approval Date:	JUL 02 2013
Expiration Date:	
Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Like approval by
BLM

2RP-1694