

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 06 2013

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company COG OPERATING LLC 229/37 Contact Pat Ellis
Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077
Facility Name PINTO 36 STATE COM #004H Facility Type TANK BATTERY

Surface Owner STATE Mineral Owner Lease No. (API#) 30-015-40058

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| P | 36 | 18S | 25E | | | | | EDDY |

Latitude 32.69766

Longitude 104.43324

NATURE OF RELEASE

| Type of Release | Oil and produced water | Volume of Release | 3bbls of oil 12bbls of produced water | Volume Recovered | 3bbls of oil 11bbls of produced water |
|-----------------------------|--|---|--|----------------------------|--|
| Source of Release | Hole in 4" production line | Date and Hour of Occurrence | 06-01-2013 | Date and Hour of Discovery | 06-01-2013 12:00pm |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | | Date and Hour | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole in the bottom of a 4" production occurred due to corrosion. The line has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially 3bbls oil and 12bbls of produced water were released to a corroded 4" line. We were able to recover 3bbls of oil and 11bbls of produced water with a vacuum truck. The entire release was contained inside the lined facility. All free fluids have been recovered. Any contaminated gravel has been removed, the liner has been washed, and we have replaced with clean gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Robert Grubbs Jr.*

Printed Name: Robert Grubbs Jr.

Title: Senior Environmental Coordinator

E-mail Address: rgrubbs@concho.com

Date: 06-05-2013 Phone: 432-661-6601

Approved by District Supervisor Signed By *Alto Benavides*

Approval Date: JUN 14 2013

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1681